

AVIATION SAFETY NETWORK


AN EXCLUSIVE SERVICE OF FLIGHT SAFETY FOUNDATION

Home | Database | Investigation | Statistics | Contact us | About |    

Home » ASN Aviation Safety WikiBase

This information is added by users of ASN. Neither ASN nor the Flight Safety Foundation are responsible for the completeness or correctness of this information. You can contribute by [submitting additional or updated information](#).

Date: Friday 7 August 1970
Time:



Type: [North American Rockwell OV-10A Bronco](#)
Owner/operator: United States Navy
Registration: 155460
MSN: 305-71
Fatalities: Fatalities: 2 / Occupants: 2
Other fatalities: 0
Aircraft damage: Destroyed
Location: NAS North Island, CA -  [United States of America](#)
Phase: Approach
Nature: Military
Departure airport:
Destination airport: NAS North Island, CA/V5-41
Narrative:

Crashed on beach. Instructor Lt William J. Leebern (29) and student Lt Thomas E. Lang (25) ejected too low and died.

Sources:

San Bernardino Sun 8 August 1970, pA18
http://web.archive.org/web/20160917114715/http://www.ejection-history.org.uk:80/Aircraft_by_Type/OV_10_BRONCO.htm

Revision history:

Date/time	Contributor	Updates
23-Nov-2011 12:00 UTC	Dr. John Smith	Added
06-Oct-2014 20:15 UTC	Booshka823	Updated [Operator,]
14-Mar-2015 06:40 UTC	VAL-4	Updated [Source, Narrative,]
28-Feb-2022 13:59 UTC	TB	Updated [Operator, Location, Phase, Destination airport, Source, Narrative,]

Corrections or additions? ... [Edit this accident description](#)

The Aviation Safety Network is an exclusive service provided by:

Quick Links:

- ASN Home
- Send Correction / Feedback
- FSF Home
- Disclaimer
- Copyright
- Contact Us
- Privacy Policy
- Press / Media



1920 Ballenger Av, 4th Fl.
Alexandria, Virginia 22314
www.FlightSafety.org

CONNECT WITH US:     

©2026 Flight Safety Foundation